

**GOVERNMENT OF KARNATAKA
DEPARTMENTS OF PUBLIC WORK,**

EXECUTIVE ENGINEER, DEPARTMENTS OF PUBLIC WORK, No 3 SUB DIVISION, KANAKAPURA.
Phone No: E-mail: acepwdKanakapura63@gmail.com

No: SKA/LOE UV/KNK/SCHOOL/2023-24/262

Date: 19-08-2023

To,
The Sports School
Vaderahalli, Harohalli hobli
Kanakapura Taluk

Respected Sir,


Subject: - The Sport School, Survey No: - 99/10, 1/10, 1/11, Vaderahalli, Harohalli Hobli, Kanakapura Taluk regarding issue of building safety certificate for the school building.

Reference: - 1) Government of Karnataka Ministry of Development Building Bangalore. Circular Order No: -LOE/59/BED/2019, Dated:-07/05/2022
2) Request Dated:-16/08/2023

Regarding to the above Subject, The Sports School, Survey No: - 99/10,1/10,1/11,Vaderahalli, Harohalli Hobli, Kanakapura Taluk, requested this office in reference letter (1) as per order of reference letter (2) to issue safety certificate for schoolbuilding.

As per Karnataka Material Test House Pvt Ltd, Basaveshwara Layout, Nagashettahalli, RMV 2nd Stage(NABL Accredited Laboratory as per ISO/IEC-17025:2017) Bangalore reviewed the school building on Date:-07/08/2021 and issued the Building Quality Report on Date:-10/08/2021 in the report Rebound Hammer Test and the Ultrasonic Pulse Velocity Test, and other necessary tests have been conducted and verified that the school building is "**Structurally Stable**".

Continued Date:- On 17-08-2023 Joint Inspection was done for the above said school building along with the School Principal as per the reports given by Karnataka Material Test House Pvt Ltd, Basaveshwara Layout Nagashettahalli, RMV 2nd Stage(NABL Accredited Laboratory as per ISO/IEC-17025:2017) Bangalore on considering the certificate given as "**Structurally Stable**". As per Government circular of reference letter (1) and fixing the fee for issuing building safety certificate in reference letter (2) dated:-16/08/2023 DD No:- 018021 State Bank of India, Harohalli for Rs. 1000.00 (One Thousand only) DD has been submitted to this office.




The Sport School, Survey No: -99/10,1/10, 1/11, Vaderahalli, Harohalli Hobli, Kanakapura Taluk regarding the safety of the school building the following deficiencies are suggested to be adopted from time to time.

- 1) Plastering and Painting to Existing Roof Slab and Walls.
- 2) Damp Proofing Works at All Floors.
- 3) Crack Sealing or Grouting Works at Visible Structural Cracks at Some Locations.
- 4) Crack Sealing works at visible hairline cracks at some locations of wall and Column/Beam Junctions.
- 5) Damp Proofing works to Toilet Block and repair works to avoid leakages in sanitary lines.
- 6) Safety Measures for Students and others.
- 7) Grill works to staircase area.
- 8) This Certificate is not Valid incase of any kind of natural disaster like Cyclone & Earth quake/Man-made disaster, any addition & alternation of Building.
- 9) As Per Karnataka Material Test House Pvt Ltd,Basaveshwara Layout,Nagashettahalli, RMV 2nd Stage Bangalore Report this Certificate is valid for 3 years.
- 10) Public Works Department is not responsible for ownership of property.

"Fire Safety Certificate" issued by District Fire Officer, Ramanagara Fire Station, Basavanapura, Ramanagara Dist vide no:-35/DFO/RMFS/FSCC/2023 dated:-28/06/2023. A Safety Certificate has been issued that the building is "**Structurally Stable**" based on the reports of the said building, correction of the above deficiencies from time to time and inspections.

Yours faithfully

Assistant Executive Engineer,
Public Works Department,
No.3 Sub-Division,
Kanakapura



[Handwritten Signature]

PRINCIPAL
THE SPORTS SCHOOL
No. 92, Vaderahalli, 19th Mile,
Harohalli (H), Kanakapura Main Road,
BENGALURU - 562 112

Translated by me
[Handwritten Signature]
21/8/2023

KANTHARAJU. S B.A.L.L.B
NOTARY PUBLIC
GOVT OF INDIA
Doddaman. gu. Doddi,
asaba (H), Ramanagara T. & Dist-562159



ಕರ್ನಾಟಕ ಸರ್ಕಾರ

ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್ ರವರ ಕಛೇರಿ,ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ನಂ.3 ಉಪವಿಭಾಗ, ಕನಕಪುರ.

Phone No:

E-Mail:aeepwdKanakapura63@gmail.com

ಸಂಖ್ಯೆ: ಸಕಾಅ/ಲೋಇಉವಿ/ಕನಕ/ಶಾಲೆ/2023-24/262

ದಿನಾಂಕ : 19-08-2023

ರವರಿಗೆ,

ದಿ ಸ್ಟೋರ್ಟ್ ಸ್ಕೂಲ್
ವಡೇರಹಳ್ಳಿ, ಹಾರೋಹಳ್ಳಿ ಹೋಬಳಿ
ಕನಕಪುರ ತಾಲ್ಲೂಕು

ಮಾನ್ಯರೇ,

ವಿಷಯ:-ದಿ ಸ್ಟೋರ್ಟ್ ಸ್ಕೂಲ್, ಸರ್ವೆ ನಂ:- 99/10,1/10,1/11, ವಡೇರಹಳ್ಳಿ, ಹಾರೋಹಳ್ಳಿ ಹೋಬಳಿ, ಕನಕಪುರ ತಾಲ್ಲೂಕು ಶಾಲಾ ಕಟ್ಟಡಕ್ಕೆ ಕಟ್ಟಡ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡುವ ಬಗ್ಗೆ.

ಉಲ್ಲೇಖ:-1)ಕರ್ನಾಟಕ ಸರ್ಕಾರದ ಸಚಿವಾಲಯ ವಿಕಾಸ ಸೌಧ ಬೆಂಗಳೂರು ರವರ ಸುತ್ತೋಲೆ ಆದೇಶ ಸಂಖ್ಯೆ:-ಲೋಇ/59/ಬಿಇಡಿ/2019, ದಿನಾಂಕ:-07/05/2022
2)ತಮ್ಮ ಮನವಿ ದಿನಾಂಕ:-16/08/2023

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ದಿ ಸ್ಟೋರ್ಟ್ ಸ್ಕೂಲ್, ಸರ್ವೆ ನಂ:- 99/10,1/10,1/11, ವಡೇರಹಳ್ಳಿ, ಹಾರೋಹಳ್ಳಿ ಹೋಬಳಿ, ಕನಕಪುರ ತಾಲ್ಲೂಕು ಶಾಲಾ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಲು ಉಲ್ಲೇಖ ಪತ್ರ (1) ರ ಆದೇಶದ ಪ್ರಕಾರ ಉಲ್ಲೇಖ ಪತ್ರ (2)ರಲ್ಲಿ ಈ ಕಛೇರಿಯನ್ನು ಕೋರಿರುತ್ತಿರಿ.

ಅದರಂತೆ Karnatak Material Test House Pvt Ltd,Basaveshwara Layout Nagashettahalli, RMV 2nd Stage(NABL Accredited Laboratory as per ISO/IEC-17025:2017) ಬೆಂಗಳೂರು ರವರು ದಿನಾಂಕ:-07/08/221 ರಂದು ಶಾಲೆಯ ಕಟ್ಟಡವನ್ನು ಪರಿಶೀಲಿಸಿ ಕಟ್ಟಡದ ಗುಣಮಟ್ಟ ವರದಿಯನ್ನು ದಿನಾಂಕ:-10/08/2021 ರಂದು ನೀಡಿದ್ದು ವರದಿಯಲ್ಲಿ ರಿಬೋಂಡ್ ಹ್ಯಾಮರ್ ಟೆಸ್ಟ್, ಮತ್ತು ಆಲ್ಟ್ರಾಸಾನಿಕ್ ಪಲ್ಸ್ ವೆಲಾಸಿಟಿ ಟೆಸ್ಟ್, ಹಾಗೂ ಅಗತ್ಯವಿರುವ ಇನ್ನಿತರ ಟೆಸ್ಟ್‌ಗಳನ್ನು ಮಾಡಿ ಶಾಲಾ ಕಟ್ಟಡವು "structurally Stable" ಇರುವುದಾಗಿ ವರದಿ ನೀಡಿರುತ್ತಾರೆ.

ಮುಂದುವರೆದು ದಿನಾಂಕ:-17-08-2023 ರಂದು ಸದರಿ ಶಾಲೆಯ ಕಟ್ಟಡವನ್ನು ಶಾಲೆಯ ಮುಖ್ಯೋಪಾಧ್ಯಾಯರೊಡನೆ ಜಂಟಿ ಪರಿಶೀಲನೆ ನಡೆಸಲಾಗಿ ಸದರಿ ಕಟ್ಟಡವನ್ನು Karnatak Material Test House Pvt Ltd,Basaveshwara Layout Nagashettahalli, RMV 2nd Stage(NABL Accredited Laboratory as per ISO/IEC-17025:2017) ಬೆಂಗಳೂರು ರವರು "structurally Stable" ಎಂದು ನೀಡಿರುವ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಪರಿಗಣಿಸಿ ಹಾಗೂ ಉಲ್ಲೇಖ ಪತ್ರ (1)ರ ಸರ್ಕಾರದ ಸುತ್ತೋಲೆಯಂತೆ ಕಟ್ಟಡ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಲು ಶುಲ್ಕ ನಿಗದಿಪಡಿಸಿದನ್ವಯ ಉಲ್ಲೇಖ ಪತ್ರ (2)ರಲ್ಲಿ ದಿನಾಂಕ:-16/08/2023 ರಂದು ಡಿ.ಡಿ.ಸಂ:-018021 State Bank of India ಹಾರೋಹಳ್ಳಿ ರವರಿಂದ ರೂ;-1000.00 (ರೂ. ಒಂದು ಸಾವಿರಗಳು ಮಾತ್ರ)ರ ಡಿ.ಡಿ.ಯನ್ನು ಈ ಕಛೇರಿಗೆ ಸಲ್ಲಿಸಿರುತ್ತೀರಿ.

ದಿ ಸ್ಟೋರ್ಟ್ ಸ್ಕೂಲ್, ಸರ್ವೆ ನಂ:-99/10,1/10,1/11, ವಡೇರಹಳ್ಳಿ, ಹಾರೋಹಳ್ಳಿ ಹೋಬಳಿ, ಕನಕಪುರ ತಾಲ್ಲೂಕು ಶಾಲಾ ಕಟ್ಟಡದ ಸುರಕ್ಷತೆಗೆ ಸಂಬಂಧಿಸಿದಂತೆ ಈ ಕೆಳಕಂಡ ನ್ಯೂನತೆಗಳನ್ನು ಕಾಲ ಕಾಲಕ್ಕೆ ಅಳವಡಿಸಿಕೊಳ್ಳಲು ಸೂಚಿಸಲಾಗಿದೆ

1. Plastering and Painting to Existing Roof Slab and Walls.
2. Damp Proofing Works at All Floors.
3. Crack Sealing or Grouting Works at Visible Structural Cracks at Some Locations.
4. Crack Sealing works at visible hairline cracks at some locations of wall and Column/Beam Junctions.
5. Damp Proofing works to Toilet Block and repair works to avoid leakages in sanitary lines.
6. Safety Measures for Students and others.
7. Grill works to staircase area.
8. This Certificate is not Valid incase of any kind of natural disaster like Cyclone & Earth quake/Man-made disaster, any addition & alternation of Building.
9. As Per Karnataka Material Test House Pvt Ltd,Basaveshwara Layout Nagashettahalli, RMV 2nd Stage Bangalore Report this Certificate is valid for 3 Years.
10. ಸ್ವತ್ತಿನ ಮಾಲಿಕತ್ವದ ಹಕ್ಕಿನ ಬಗ್ಗೆ ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ಜವಾಬ್ದಾರರಾಗಿರುವುದಿಲ್ಲ.

“Fire Safety Certificate” ಅನ್ನು District Fire Officer, Ramanagara Fire Station, Basavanapura, Ramanagara Dist ರವರ ಪತ್ರ ಸಂ:-35/DFO/RMFS/FSCC/2023 ದಿನಾಂಕ:-28/06/2023 ರಲ್ಲಿ ನೀಡಿರುತ್ತಾರೆ. ಸದರಿ ಕಟ್ಟಡದ ವರದಿಗಳ, ಮೇಲ್ಕಂಡ ನ್ಯೂನತೆಗಳನ್ನು ಕಾಲ ಕಾಲಕ್ಕೆ ಅಳವಡಿಸಿಕೊಳ್ಳಲು ಹಾಗೂ ತಪಾಸಣೆಗಳ ಆಧಾರದ ಮೇಲೆ ಕಟ್ಟಡವು “structurally Stable” ಇದೆ ಎಂದು ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು,
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ನಂ.3 ಉಪ ವಿಭಾಗ,
ಕನಕಪುರ



SELF DECLARATION

I, **Ms. Jayapriya, the Principal of The Sports School**, do hereby state that the building safety certificate numbered 1/2021-2022/667 had to be re issued because of clerical error.

The updated building safety certificate has been enclosed for your reference.

I hereby confirm that whatever has been stated above is true and correct to the best of my knowledge, information and belief.


PRINCIPAL
PRINCIPAL
THE SPORTS SCHOOL
No. 92, Vaderahalli, 19th Mile,
Harohalli (H), Kanakapura Main Road,
BENGALURU - 562 112



A R K A

ARKA Educational and Cultural Trust

BOARD RESOLUTION

EXTRACT OF MINUTES OF THE MEETING OF TRUSTEES HELD ON 16 AUGUST 2023 IN REGISTERED OFFICE BANGALORE

The Managing Trustees explained to the Board the lease land bearing the survey no: 1/10, 1/11, 99/10 located at The Sports School, Vaderahalli, Harohalli Hobli, Kanakapura Taluk, Ramanagara District, Karnataka is fully allocated for School purpose only.


Authorized Signatory

Registered Office :

#91/2, Dr.A.N. Krishna Road Road,
V.V. Puram, Bengaluru-560004.
Karnataka