



ಕಗ್ಗಲಹಳ್ಳಿ ಗ್ರಾಮ ಪಂಚಾಯಿತಿ ಕಾರ್ಯಾಲಯ

ಹಾರೋಹಳ್ಳಿ ಹೋಬಳಿ, ಕನಕಪುರ ತಾಲ್ಲೂಕು, ರಾಮನಗರ ಜಿಲ್ಲೆ-562 112

ಇ-ಮೇಲ್: kaggalahalligppdo@gmail.com



No: KGP/18/Drinking Water/2024-2025

Dated: 11/07/2024

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

It is certified that an inspection team headed by Smt.SRIDEVI B C (PANCHAYAT DEVELOPMENT OFFICER) from Kaggalahalli Grama Panchayat Inspected THE SPORTS SCHOOL, S.Y. NO. 1/10,1/11, VADERAHALLI, HAROHALLI HOBLI, KARNATAKA, RAMANAGARA 562112 on 29/06/2024 and on the basis of Water Test Report bearing no: VL/2405/2262 dated 01/06/2024 of VSIX ANALYTICS LABS PVT LTD. certified that THE SPORTS SCHOOL has safe drinking water facilities for the students and members of staff of the institution. School is also maintains the hygienic sanitation condition in the school building and the campus as per norms prescribed by the Central/State/U.T. Govt.

THIS CERTIFICATE IS VALID TILL 5 YEARS.

Signature with Seal: _____

Name: ಪಂಚಾಯಿತಿ ಅಭಿವೃದ್ಧಿ ಅಧಿಕಾರಿ

Designation: ಕಗ್ಗಲಹಳ್ಳಿ ಗ್ರಾಮ ಪಂಚಾಯಿತಿ

Name & Address of the Office/Department: ಕನಕಪುರ ತಾಲ್ಲೂಕು.

To,
THE SPORTS SCHOOL
S.Y. no. 1/10,1/11, Vaderahalli,
Harohalli Hobli,
Karnataka,
Ramanagara 562112

PANCHAYAT DEVELOPMENT
OFFICER
Kaggalahalli Grama Panchayat
Kanakapura Taluk